

Como borrar el plugin en cámaras HD (Windows / MAC) valido para firmware 2.x.1.10 o superior

Desde Windo ws

1. Haga clic en el botón Inicio de su escritorio y acceda al Panel de Control



Imagen 1

2. Seleccione ver por Categoría y Agregar o quitar programas .

×





Imagen 2

3. Busque en el listado IPCWebComponents y haga clic con el botón derecho para des instalar

View installed updates Turn Windows features on or off	To uninstall a program, select it fr	om the list and then	click Uniostall Change of Repair								
Turn Windows features on or off	To uninstall a program, select in in	form the lise and then	To unjectill a program relact it from the list and then click linestall Change or Renair								
off	0	to uninsian a program, select a trom the nst anu then cuck uninstant, change, or nepan.									
	Organize + Uninstall III										
	Name		Publisher	Installed On	Size	Version					
	Broadcom 80211 Network Adapte		Broadcom Corporation	2014/5/2		5 100 240 2					
	Readcom Gigshit Methick Control	der.	Broadcom Corporation	2014/5/2	100 VP	14.2.4.2					
	Cambraia Chudia 8	Jer -	Task mak Corporation	2014/3/2	409 KB	0.201471					
	Circo EAD EAST Madula		Cisco Sustema Inc.	2014/0/0	1 15 MD	2.2.14					
	Circo LEAD Module		Cisco Systems, inc.	2014/3/2	1.13 MB	1,019					
	Cisco PEAP Module		Cisco Systems, Inc.	2014/5/2	932 KB	116					
	Deenhor		Cisco systems, inc.	2014/3/2	364 60	294					
	T CILAS		空田高市町立体和188日以前	2014/5/3		2407					
	Clark Chart 20 Ocharts 2		Tim Korra	2014/5/5	24.4.449	200-64-2					
	FileZilla Server		FileZilla Project	2014/5/5	5.02 MB	heta 0.9.44					
	E Filezilia Seven		EDECAM	2014/5/23	25.5 MR	1 4 1 2					
	Cocole Chrome		Google Inc	2014/5/8	25.5 mb	35.0 1016 114					
	Distal® Panid Storage Technology		Intel Composition	2014/5/3		120 21000					
	The Intel what is a storage recting of the		antei Corporation	2014/5/25	3.67 MD	2001					
L	Microsoft NET Ecomound 451	Uninstall	licrosoft Corporation	2014/6/20	20 0 MD	4.5.50028					
	Microsoft Visual Care 2009 Pedicted	5 0.0 39	Microsoft Corporation	2014/3/5	30.0 MD	4.3.30556					
	Microsoft Visual C++ 2008 Redistri	Jutable - Nou 970.0	Microsoft Corporation	2014/5/4	210 10	9/0.30729					
	Microsoft visual C++ 2008 Kedistrie	30table - x80 970.5	Microsoft Corporation	2014/5/2	350 KB	30.30729.4148					
	Mozilla Maintagana Conica		Mazilla	2014/0/23	07.3 MB	30.0					
	Mozilia Maintenance Service		IV902IIIB	2014/5/0	225 KB	200					
	Protecting instantia		Bachah Camina duntas Cam	2014/0/30	4.90 MB	6016650					
	Resident High Deficition Audio Driver for All	2.4	Realized Semiconductor Corp.	2014/5/2		6.01.6600					
	Schenz 216 16		Share Technologies C.A.	2014/3/2	261140	6 16 105					
	Skype - 0.10		Skype Technologies S.A.	2014/0/0	20.1 MD	16.210.105					
	Synaptics Pointing Device Univer		Synaptics incorporated	2014/3/2	40.4 MD	10.210.19					
	Teamviewer a		reamviewer	2014/0/24		91/23400					

Imagen 3



Control Panel Home View installed updates Turn Windows features on or off	Uninstall or change a program To uninstall a program, select it from the list and then click Uninstall, Change, or Repair.							
	Organize + Uninstall							
	Name	Publisher	Installed On	Size	Version			
	Constain Studie 3 Constain Studie 3 Constain Studie 3 Constain Studie 3 Conscient Studie 3	Broadcom Corporation Broadcom Corporation TechSmith Corporation Cisco Systems, Inc. Cisco Systems, Inc.	2014/5/2 2014/5/2 2014/6/8 2014/5/2 2014/5/2	409 KB 369 MB 1.15 MB 492 KB	5.100.249.2 14.2.4.2 8.3.0.1471 2.2.14 1.0.19			
			remove PCWebComponents and					
	Cicco PEAP Module Cicco PEAP M	IPCWebComponents Uninstall	ly remove IPCWeb	Components a	ind 14			

Imagen 4

Control Panel Home	Uninstall or change a program							
View installed updates Turn Windows features on or off	To uninstall a program, select it from the list and the	6						
	Organize + Uninstall							
	Name	Publisher	Installed On	Size	Version			
	Broadcom 802.11 Network Adapter Broadcom Gigabit NetLink Controller Camtasia Studio 8 Cisco EAP-FAST Module Cisco LEAP Module	Broadcom Corporation Broadcom Corporation TechSmith Corporation Cisco Systems, Inc. Cisco Systems, Inc.	2014/5/2 2014/5/2 2014/6/8 2014/5/2 2014/5/2	409 KB 369 MB 1.15 MB 492 KB	5100.249.2 14.2.4.2 8.3.0.1471 2.2.14 1.0.19			
	Cisco PEAP Module Dopbor Dopbor Disco PEAP Module Disco PEAP Modu	omponents Uninstall	fully removed fro	m your comput	ег. 2 8 К. 0			
	Microsoft NIT Framework 4.5.1 Microsoft Visual C + 2008 Redistributable - 466 9.0.3. Microsoft Visual C + 2008 Redistributable - 466 9.0.3. Mozilla Firefor 300 (466 en-U5) Mozilla Maintenance Service NVRPlugint 1.0.01 Mealtek H0M Audio Driver for ATT Mateutic High Definition Audio Driver Spage* 8.15 Synaptics Pointing Device Driver	Microsoft Corporation Microsoft Corporation Mozilla Mozilla Realtek Semiconductor Corp. Realtek Semiconductor Corp. Skype Technologies S.A. Synaptics Incorporated	2014/3/3 2014/5/4 2014/5/2 2014/6/23 2014/5/8 2014/5/8 2014/5/2 2014/5/2 2014/5/2	26.1 MB 240 KB 596 KB 67.5 MB 225 KB 4.95 MB 26.1 MB 46.4 MB	9.0.30729 9.0.30729 9.0.30729.4148 30.0 29.0 1.0.0.1 60.1.6650 60.1.6543 61.6105 16.210.19			

Imagen 5

4. En este momento ya ha borrado el plugin antiguo con éxito.

Desde MAC

Si desea borrar los plugin desde Safari abra una ventana de búsqueda en la barra de menú y acceda a $Go \rightarrow Ir a Carpeta$

Copie y pegue el siguiente texto: Liberia / Plugins Internet

Haga clic en **Ir** para moverse a la carpeta de plugins



O mantenga pulsada la tecla **Option** desde **Libreria** y acceda a **"Plugin de Internet"** Localice el fichero IPCam.bundle y para borrarlo.

La cámara le preguntará instalar la ultima versión la próxima vez inicie.

Nota: No inicie su cámara mientras borra el fichero, ya que el plugin no podrá ser borrado si esta en uso.

